



Activation of VP0131w




Fig. 1a



Bleaching of VP0131w




Fig. 1b



Activation of VP0215 in PU




Fig. 2a



Bleaching of VP0215 in PU





Fig. 2b



**Activation of VP0243-A in PU
(VP0243B purified with SiO₂ and Al₂O₃ LC)**



**Bleaching of VP0243-A in PU (1%)
(VP0243B purified with SiO₂ and Al₂O₃ LC)**





Fig. 3a



Activation of VP0243A in PU



Bleaching of VP0243A in PU (0.2%)





Fig. 3b



**Activation of VP0243B in PU
(VP0243B purified with SiO₂ LC only)**



**Bleaching of VP0243B in PU (1%)
(VP0243B purified with SiO₂ LC only)**




Fig. 3c